



Pressure Vs Torque Conversion Chart

TPS TS-10 Square Drive Torque Wrench

Pressure	Torque	Pressure	Torque	
Psi	Ft-Lb	Bar	Kgm	Nm
1000	1097	69	152	1487
1200	1317	83	182	1786
1400	1536	97	212	2083
1600	1760	110	243	2386
1800	1982	124	274	2687
2000	2203	138	305	2987
2200	2428	152	336	3292
2400	2649	166	366	3592
2600	2877	179	398	3901
2800	3102	193	429	4206
3000	3328	207	460	4512
3200	3551	221	491	4815
3400	3775	234	522	5118
3600	3998	248	553	5421
3800	4224	262	584	5727
4000	4448	276	615	6031
4200	4673	290	646	6336
4400	4895	303	677	6637
4600	5119	317	708	6940
4800	5342	331	739	7243
5000	5565	345	769	7545
5200	5785	359	800	7843
5400	6009	372	831	8147
5600	6233	386	862	8451
5800	6456	400	893	8753
6000	6679	414	923	9056
6200	6901	428	954	9357
6400	7123	441	985	9657
6600	7344	455	1015	9957
6800	7565	469	1046	10257
7000	7787	483	1077	10558
7200	8007	497	1107	10856
7400	8224	510	1137	11150
7600	8442	524	1167	11446
7800	8654	538	1196	11733
8000	8871	552	1226	12027
8200	9074	566	1255	12303
8400	9289	579	1284	12594
8600	9505	593	1314	12887
8800	9722	607	1344	13181
9000	9939	621	1374	13475
9200	10152	634	1404	13764
9400	10369	648	1434	14058
9600	10567	662	1461	14327
9800	10776	676	1490	14610
10000	10985	690	1519	14894