



Pressure Vs Torque Conversion Chart

TPS TS-20 Square Drive Torque Wrench

Pressure	Torque	Pressure	Torque	
Psi	Ft-Lb	Bar	Kgm	Nm
1000	1821	69	252	2469
1200	2185	83	302	2962
1400	2549	97	352	3456
1600	2916	110	403	3954
1800	3283	124	454	4451
2000	3652	138	505	4951
2200	4019	152	556	5449
2400	4436	166	613	6014
2600	4829	179	668	6547
2800	5223	193	722	7081
3000	5627	207	778	7629
3200	6011	221	831	8150
3400	6396	234	884	8672
3600	6788	248	938	9203
3800	7185	262	993	9742
4000	7601	276	1051	10306
4200	7999	290	1106	10845
4400	8397	303	1161	11385
4600	8755	317	1210	11870
4800	9124	331	1261	12370
5000	9493	345	1312	12871
5200	9875	359	1365	13389
5400	10268	372	1420	13922
5600	10674	386	1476	14472
5800	11068	400	1530	15006
6000	11445	414	1582	15517
6200	11818	428	1634	16023
6400	12195	441	1686	16534
6600	12579	455	1739	17055
6800	12968	469	1793	17582
7000	13357	483	1847	18110
7200	13752	497	1901	18645
7400	14141	510	1955	19173
7600	14530	524	2009	19700
7800	14926	538	2064	20237
8000	15315	552	2117	20764
8200	15710	566	2172	21300
8400	16099	579	2226	21827
8600	16488	593	2280	22355
8800	16883	607	2334	22890
9000	17272	621	2388	23418
9200	17662	634	2442	23946
9400	18056	648	2496	24481
9600	18446	662	2550	25009
9800	18840	676	2605	25544
10000	19230	690	2659	26072